

Thickener Discharge Cones

Mining/Mineral & Ore Processing — Beneficiation ARC MX1 & 855 Coatings Case Study 110

Challenge

Issue

The delamination of ceramic tiles clog suction valve and thickener extraction pump, and require unscheduled draining at 12-18 months with associated maintenance costs. Attempted test repairs with rubber linings failed.

Goals

- Eliminate blockage of valve and pump
- Increase shut down cycle to >24 months

Root Cause

Discharge slurry wears grout lines (causing tile delamination) and tears rubber lining at seams.



Thickener discharge cone

Solution

Preparation

- Hydro-blast removal of rubber lining
- Grit blast to Sa 2.5 with 3 mil (75 μm) angular profile

Application

- 1. Apply ARC MX1 @ 500-750 mil (12-18 mm)
- 2. Overcoat with ARC 855 @ 15-20 mils (375-500 μ m)

Results

Client Reported

- Service life extended to >24 months
- Unscheduled maintenance cost avoidance* \$50,000 per 18 month cycle
- Client specified ARC MX1 for 16 additional CCD exit cones

*Cost avoidance: cleanout, rubber lining, downtime

\$=USD



ARC 855 over coat



Application of ARC MX1